


Before 32 cavity PM with leaks




Assembly views after cleaning & components inspection / extrude honing




Completed view / crated for shipment



Before 48 cavity



Front view /



Before




After (Cold sprue modified to hot)




Crated for shipment





After during assembly 48 drops / 4 sub man.




4 Submanifolds / 1 Bridge (57 zones) complete over haul.




Before / 64 drop Stack



After




Before 64 cavity / 4 sub manifold / 1 bridge flood




After during assembly / views


Drops, heaters and thermocouples installed after cleaning / inspection




4 Sub manifolds installed



Bridge installed



Special electrical connection and completed for crating.




All of the above jobs were completed with repairs in 7-10 business days, or sooner.



**Thermal-Tech
Systems, Inc.**

Plate cleaning
Before



After

